Form 11 - Soil Evaluator Form

Commonwealth of Massachusetts VLSE Job #188-13

Town of: Chilmark

Soil Suitability Assessment for On-Site Disposal

Performed By: Reid Silva Date of Test: 12/22/2022

Witnessed By: Anna McCaffrey

Location A/P: 2-1 Owner Name: Sarah Leahy

Location Address: #89 Harlock Pond Road c/o Vineyard Land Surveying and Eng.

Type of Construction: Upgrade P.O. Box 421, Cournoyer Rd.

West Tisbury, MA 02575

(508) 693-3774

Office Review

Published Soil Survey Available: YES

Year Published - 1986 Publication Scale - 1:20000 Soil Limitations: None

Soil Information: 285B - Eastchop loamy sand, 3 to 8 percent slopes, very stony - EdB

Surficial Geologic Report Available: YES Drainage Class: ED

Year Published: 1986 Publication Scale: N/A

Geologic Material (map unit) and Landform: Qmv - Martha's Vineyard Moraine

Flood Insurance Rate Map

Above 500 year flood boundary: Yes Within 500 year flood boundary: No Within 100 year flood boundary: No

Wetland Area

National Wetland Inventory Map (map unit): N/A

Wetlands Conservancy Program Map (map unit): N/A

Current Water Resource Conditions (USGS)

Range: Below Normal Month: November

Other References Reviewed: Groundwater Hydrology of Martha's Vineyard, Mass. Delaney, 1980

Location Address or Lot No. #89 Harlock Pond Road Chilmark

A/P: <u>2-1</u> VLSE Job #188-13

Deep Hole Number: 1 Date: 12/22/2022 Time: Mid Day Weather: Clear

Slope: 3 to 8 Landuse: Residential Vegetation: Grass

Hole Location. Position on Landscape, Distances from Open Water Body, Possible Wet Area,

Drinking Water Well, Drainage way, Property Line (SEE PLAN)

DEEP HOLE OBSERVATION LOG						
	Depth from Surface (inches)	Soil Horizon	Soil Texture (USDA)	Soil Color (Munsell)	Soil Mottling	Other (Structure, Stones, Boulders, Consistncy, % Gravel)
TH #1	0 - 10	Α	Sandy Loam	Х	Х	Perc. Rate < 5 MPI @ 80 "
	10 - 40	В	Loamy Sand	Х	Х	Groundwater: NO GW found at Elev. = 94.2
	40 - 80	C1	Silt Loam	Х	Х	
	80 - 144	C2	Medium Coarse Sand	Х	Х	
						<u></u>
						-
						-
Parent Material (geologic): Moraine Depth to Bedrock: N/A						
Depth to Groundwater Information: Weeping From Pit Face: N/A						
Standing Water in the Hole: <u>No</u>						
Estimated Seasonal High Ground Water: > 12' below test hole #1						
Does at least four feet of naturally occurring pervious material exist in all areas observed throughout the area proposed						
for the soil absorbtion system? YES						
If not, what is the depth of the naturally occurring pervious material? N/A						
I certify that on 11/22/2002 - rs I have passed the soil evaluator examination approved by the Department of Environmental						
Protection and that the above analysis was performed by me consistent with the required training, expertise and experience described						
in 310 CMR 15.017						
		17.	11	/		
Signature: Date: December 22, 2022						