FORM 11 - SOIL EVALUATOR FORM

Page 1 of 3

No.

Date: Aug. 29, 2023

Commonwealth of Massachusetts

Chilmark , Massachusetts

1

Soil Suitability Assessment for On-site Sewage Disposal

Performed By: Reid Silva		Date: Marc	h 2 <u>2, 2021</u>
Witnessed By: Marina Lent			
Location Address or #7 North Abel's Hill Road (Part of Assr. Pcl. 24-161)	Telephone P.O. Bo	Realty Trust neyard Land Surveying ox 421, Cournoyer Rd. isbury, MA 02575	
New Construction 🖾 Repair 🔲		3-3774	
Office Review Published Soil Survey Available: No Yes Year Published 1986 Drainage Class ED Soil Limitations	1.20000	Soil Map Unit	EcC
Surficial Geologic Report Available: No 🗌 Yes	ζ		
Year Published Publication Scale Geologic Material (Map Unit)	Qgh		t
Landform Gay Head Morall Flood Insurance Rate Map:	10		
Above 500 year flood boundary No Yes X			
Within 500 year flood boundary No XYes			
Within 100 year flood boundary No XYes			
Wetland Area: National Wetland Inventory Map (map unit) Wetlands Conservancy Program Map (map unit)	······································	N/A N/A	
Current Water Resource Conditions (USGS): Month Range : Above Normal Normal X Belcy Normal	, 1 🗆	·····	
Other References Reviewed: Groundwater Hydrolog	y of Martha's V	Vineyard, Mass. Dela	ney, 1980



DEP APPROVED FORM - 12/07/95

Page 2 of 3

#7 North Abel's Hill Road
(Part of Assr. Pcl. 24-161)

Location Address or Lot No.

Drinking Water Well _____ feet

On-site Review

Deep Hole Number 1+2 Date	<u>: March 22, 2021</u> T	ime: Mid Day	Weather Clear	5
Location (identify on site plan)		n g na casa san naman kan		an again a an
Land Use Residential	Slope (%) 8 to 15	Surface Stones	· · · · · · · · · · · · · · · · · · ·	
Vegetation Woods	1 m ² 4 k	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	in star	e a tr
Landform	5 x x 2			, *
Position on landscape (sketch on th	e back)	5 · 2 · . · · · · · · ·		5 2 64
Distances from: See Plan				
Open Water Body 🛛 ——	feet Drainage	way — feet		
Possible Wet Area	feet Property	Line feet		

Other

Depth from Surface (Inches	Soil Horizon	Soil Texture (USDA)	Soil Color (Munsell)	Soil Mottling	Other (Structure, Stones, Boulders, Consistency, Gravel)	
0" - 8"	А	S/L	Х	Х		
8" - 32"	» В	S/L	х	Х	Perc. Rate < 5 MPI @ 60" No Groundwater Found @ 120" Elevation 70.2	
32" - 60"	C1	S/L	х	х		
60"-108"	· CŻ	M/C S	х	Х		
108"-120"	C3	F.S.	x	х	3	
0" - 10"	А	S/L	х	х		
10" - 34"	В	L/S	x	х	Perc. Rate < 5 MPI @. 96"	
34" - 98"	C1	L/S	X	х	No Groundwater Found @ 138" Elevation 70.3	
98"-138"	C2	M/C S	х	х		

 Parent Material (geologic)
 Outwash
 DepthtoBedrock:
 N/A

 Depth to Groundwater:
 Standing Water in the Hole:
 N/A
 Weeping from Pit Face:
 N/A

 Estimated Seasonal High Ground Water:
 >10' Below Test Hole #1 Elevation 70.2



DEP APPROVED FORM - 12/07/95

Location Address or Lot No.

#7 North Abel's Hill Road (Part of Assr. Pcl. 24-161)

Determination for Seasonal High Water Table

Method Used:

Depth observed standing in observation hole inches
 Depth weeping from side of observation hole inches
 Depth to soil mottles inches
 Ground water adjustment feet
Index Well Number Reading Date Index well level

Adjustment factor Adjusted ground water level

Depth of Naturally Occurring Pervious Material

Does at least four feet of naturally occurring pervious material exist in all areas observed throughout the area proposed for the soil absorption system? <u>Yes</u>

If not, what is the depth of naturally occurring pervious material? <u>N/A</u>

Certification

I certify that on $\underline{Nov 22, 2002}$ (date) I have passed the soil evaluator examination approved by the Department of Environmental Protection and that the above analysis was performed by me consistent with the required training, expertise and experience described in 310 CMR 15.017.

in A Sate Date August 29, 2023 Signature



DEP APPROVED FORM - 12/07/95